

Micron Technology,
Inc.
8000 S. Federal Way
PO Box 6
Boise, ID United
States

V00H -125 / -107 X16 IDD4R, IDD4W Specification Relaxation

PCN: 31941

Published: 2016-05-27

Type:	Datasheet Change
Description:	Micron is relaxing -107 and -125 X16 IDD4R, IDD4W specifications affecting both component and module data sheets. Refer to the component and module data sheets for details.

Anticipated Impact: Minimal to no impact.

Reason: Manufacturing Efficiency

Product Affected: V00H DDR3L X16 -107 and -125 components and modules

Affected Micron Part Number **Recommended Replacement** **Customer Part Number**

Component

MT41K256M16TW-107 AAT:P		
----------------------------	--	--

MT41K256M16TW-107 AIT:P		
----------------------------	--	--

MT41K256M16TW-107 IT:P		MT41K256M16TW-107 IT:P-ND
-------------------------------	--	--------------------------------------

MT41K256M16TW-107 XIT:P		
----------------------------	--	--

MT41K256M16TW-107:P		MT41K256M16TW-107:P- ND
----------------------------	--	------------------------------------

Module

MT4KTF25664AZ-1G6P1		
---------------------	--	--

MT4KTF25664AZ-1G9P1		
---------------------	--	--

MT4KTF25664HZ-1G6P1		
---------------------	--	--

MT4KTF25664HZ-1G6P2		
---------------------	--	--

MT4KTF25664HZ-1G9P1

MT4KTF25664HZ-1G9P2

*Materials that have been ordered are in **bold**.

Method of Identification: Date Code

Micron Sites Affected: All Sites

Qualification Plan: Per Micron standard qualification processes.

Product Ship Date: 2016-05-12

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.