



Micron
Technology,
Inc.
8000 S.
Federal
Way
PO Box 6
Boise, ID
United
States

MT28EW Parallel NOR “Secure” Flash (OTP enabled) Termination

PCN: 32630

Published: 2018-02-09

Type:	End of Life
Description:	Micron MT28EW Parallel NOR “Secure” Flash MPNs, that have OTP capability enabled, are being terminated to enable improved supply line efficiency on Micron’s NOR products. Production volumes for the impacted MPNs do not justify the continued availability. The Standard configurations of the High Lock MPNs will be the recommended Micron replacement.
Reason:	Manufacturing Efficiency
Product Affected:	MT28EW MPNs ending with -1SIT (DIDs QLHP, QLJP, QLKP, QLLP)

Affected Micron Part Number Recommended Replacement Customer Part Number

Component

MT28EW01GABA1HPC-1SIT		
MT28EW01GABA1LPC-1SIT		
MT28EW128ABA1HPC-1SIT		
MT28EW128ABA1LPC-1SIT		
MT28EW256ABA1HPC-1SIT		
MT28EW256ABA1LPC-1SIT		
MT28EW512ABA1HPC-1SIT		557-1788-ND
MT28EW512ABA1LPC-1SIT		

*Materials that have been ordered are in **bold**.

Method of	Marketing Part Number
------------------	-----------------------

Identification:

Micron Sites Affected: Fab 6 - US
MSB - Singapore

Last Purchase Date*: 2018-08-09

Last Shipment Date: 2019-02-09

*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.