Product Discontinuance Notice - PDN 12_0005 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of Select Material Numbers

| Publication Date: | 16-Feb-2012 |
|---------------------|-------------|
| Last Time Due Dates | 10 Est 0010 |

| Last Time Buy Date: | 16-Feb-2013 |
|----------------------|-------------|
| Last Time Ship Date: | 16-Feb-2014 |

Reason For Discontinuance

The product obsolescence is based on diminished customer demand for the select model(s).

Supporting Documents None

| For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive | | | | |
|---|--|-----------------------|-------------------------|--|
| Americas: PDN_Americas@analog.com Europe: | | PDN_Europe@analog.com | Japan: Rest of Asia: | PDN_Japan@analog.com PDN_ROA@analog.com |

| PDN 12_0005 Discontinued Parts Material List | | | | | |
|--|--------------------------|---|-----|----------|--|
| Model Product Family | | Replacement Part Pin To Pin Compatible | | Comments | |
| AD80118BBCZ | AD9996 | None | N/A | | |
| AD80145BBCZ | AD9923 | None | N/A | | |
| AD80145BBCZRL | AD9923 | None | N/A | | |
| AD80151BBCZRL | AD9923 | None | N/A | | |
| AD9923BBCZRL | AD9923 | AD9923ABBCZRL | Yes | | |
| ADDI9002BBCZ | ADD19002 | None | N/A | | |
| ADDI9002BBCZRL | 0002BBCZRL ADDI9002 None | | N/A | | |
| ADDI9002XBCZ ADDI9002 I | | None | N/A | | |

| Appendix A - PDN 12_0005 Revision History | | | | |
|---|--------------|-----------------|--|--|
| Rev | Publish Date | Rev Description | | |
| Rev | 16-Feb-2012 | Initial Release | | |

Analog Devices, Inc. Proprietary Information

Docld:431 Layout Rev.2 Parent Docld:None

Analog Devices, Inc. PDN 12_0005_Rev_- Page 1 of 1



MATERIALNUMBER REPLACEMENTPAI PINTOPIN COMMENTS

| AD80145BBCZ | None | N/A | Obs part not in system |
|----------------|---------------|-----|------------------------|
| AD80145BBCZRL | None | N/A | Obs part not in system |
| AD80151BBCZRL | None | N/A | Obs part not in system |
| AD9923BBCZRL | AD9923ABBCZRL | Yes | |
| AD80118BBCZ | None | N/A | Obs part not in system |
| ADDI9002BBCZ | None | N/A | Obs part not in system |
| ADDI9002BBCZRL | None | N/A | Obs part not in system |
| ADDI9002XBCZ | None | N/A | Obs part not in system |
| | | | |