



Product Discontinuation Notice: AQV258H Series PhotoMOS Relays

PDN.PG0006.1.10.2021

1.10.2021

Effective Date:	Immediate
Last Time Buy Date:	March 31, 2021
Last Eligible Ship Date:	June 30, 2021
Discontinuation Details:	The AQV258H Series PhotoMOS Relays are being discontinued.
Suggested Replacement:	AQV258H5 Series PhotoMOS Relays
Affected Part Numbers:	See Attached.
Datasheets:	See Attached.
Notes:	AQV258H5 Series PhotoMOS Relays have increased creepage distance due to the removal of the 5th pin.

Panasonic PDN.PG0006.1.10.2021 Affected Parts

Affected Series	Affected Part Numbers	Suggested Replacement Series	Suggested Replacement Part Numbers
AQV258H Series PhotoMOS Relays	AQV258H	AQV258H5 Series HE 1 Form A PhotoMOS Relays	AQV258H5
AQV258H Series PhotoMOS Relays	AQV258HA	AQV258H5 Series HE 1 Form A PhotoMOS Relays	AQV258H5A
AQV258H Series PhotoMOS Relays	AQV258HAX	AQV258H5 Series HE 1 Form A PhotoMOS Relays	AQV258H5AX
AQV258H Series PhotoMOS Relays	AQV258HAZ	AQV258H5 Series HE 1 Form A PhotoMOS Relays	AQV258H5AZ