



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000790

DATE: 08-Jan-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX13390AUP/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13391AUP/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1391ETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1391ETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1392ETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1392ETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1393ETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1393ETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1394ETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1394ETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1395ETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1396ETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1396EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8622ETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8622ETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8622EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8653ETI+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8653ETI+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8653EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1395ETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX1396ETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17022ETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17022ETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16097EWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16097EWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841HUKD1-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK46D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D3S	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D3S-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7049ATI+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7049ATI+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7049EVKIT-915#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7443ESA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7443ETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7443ETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7443EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7444ESA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7444ESA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7444ETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7450ESA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7450ESA+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7451ESA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7451ESA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7451ESA+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7452ESA+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7452EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+G05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+G071	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6855UK42D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+TC45	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+TG05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7462USA	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7462USA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7462USA-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7462UUA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7463USA	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7463USA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7463USA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7463USA-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7474EAE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7474EAE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX77577EWN+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX77577EWN+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8847YETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8847ZETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8847ZETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX8848YETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8848ZETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8848ZETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8924EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8924EWN+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9503GEEE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9503GEEE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9503GETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9503GEVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9505EEE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9505EEE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9505ETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9599AETG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9608EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9608EWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9679AETG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9679AEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695AETM+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695AETM+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695AEVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695ETM+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9699EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP+G05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP+TG05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701ETG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EUP-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+TG05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+TG24	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+TGC1	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX9789AEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK16D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK16D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK16D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK17D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK17D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK17D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK19D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK19D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK19D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789BETJ+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789BETJ+TG24	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789CETJ+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX9789CETJ+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789CETJ+TG24	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9790AETJ+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9790AETJ+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98302ETD+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98302ETD+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98302ETD+TW	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98302ETD+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98302EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98311EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98311EWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98311EWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK16D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK16D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK16D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK18D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK36D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK21D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK22D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK22D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK23D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK24D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK28D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK28D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK29D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK30D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK43D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK43D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK45D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK35D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK35D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK36D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK37D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7443ESA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7450ESA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK22D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK22D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK22D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK25D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK25D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK25D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7452ESA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+C45	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK41D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK42D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK43D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9608EWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695AETM+CBV	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP+G45	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EUP	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+TC8A	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789BETJ+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK17D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK19D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13108EEBX	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX14596EZA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14658ETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14706EVAL#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17144ETJ+C89	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19791EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14886CTL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14955ETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX15089EWG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX15577GTG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16102H2310+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16104B2916+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16106O2309IB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16106V3111MB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16110KA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16111A2916CA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16841BEVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17143ETJ+C61	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19791ETX+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK26D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK26D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK26D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK27D1	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK27D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK27D1-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK29D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK29D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK29D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK31D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK31D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK18D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2165ETI+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX2169EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2180EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2203EWT+T10	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2665EWS+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2666EYT+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2675EWT+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D3S-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3622C/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3624U/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3625C/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3636E/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3673E/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4079CUG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKMD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKRD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKSD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKWD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKYD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6781LTA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6782TEA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6784TCA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6785TCA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6786TA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841FUKD2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841FUKD4	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D3S	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK17D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK18D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK18D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK18D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19793ETX+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2062EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2063EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2117CTI+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136BETJ/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136ETJ+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136ETJ/V+TQ00	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AE/W-CG9	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ASEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ETI/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX2165EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2180ETG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2180ETG/V+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2203EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2664EWS+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2665EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2666EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2668EYT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK18D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK18D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK18D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK19D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK19D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK19D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK19D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK19D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK19D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK19D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841GUKD0+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841GUKD2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841GUKD4-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841HUKD1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841HUKD2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841HUKD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841HUKD4	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6841IUKD0	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841IUKD0-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841IUKD1-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841IUKD2-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841IUKD3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841IUKD4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6844UKD0+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6844UKD1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6844UKD2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6844UKD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6844UKD4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK16D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK16D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK16D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK17D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK17D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK17D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK35D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK35D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK35D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK35D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK35D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK35D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK35D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK36D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK36D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK36D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK36D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK36D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK36D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK21D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3678U/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2676EWT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3679AE/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3679C/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2837-RD0117	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3697C/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2838-RD0142	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2838ETM+TG05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3580ETJ+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3580EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3986UTU+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3624AE/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3625AC/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3627C/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3636E/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3671E/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3673E/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3677C/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4079EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D3S	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK23D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	ENGWV11EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500USA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500USA+G51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500USA+TG071	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500USA+TG51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500USA+TWG51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11501EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11501USA+G126	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11501USA+TG126	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11501USA+TG51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11501USA+TWG51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11502USA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11502USA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11504CUB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11504EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11505CUB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11506CEE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11506CEE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11506EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11507CEE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11508EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11508UUD+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11509UUD+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11509UUD+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13101EEBX-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13101EETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13101EETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13102EEBX	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13102EEBX-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13102EETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13103EEBX	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX13103EEBX-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13103EETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13108EETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13108EETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13374ASA/V+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13374ATA/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13374ATA/V+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14579BEETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14596EZA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14609EEWP+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14619ETT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14631EKA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14631EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14657ETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14658ETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14659ETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14659ETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14707DEMBD#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK18D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK18D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK18D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK19D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK19D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK19D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK20D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK20D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK20D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK21D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK21D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK21D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK22D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK22D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK22D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6855UK23D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK23D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK23D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK24D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK24D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK24D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK39D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK39D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK39D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK39D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK39D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK39D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK39D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK24D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK25D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AEBC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AETB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AEUB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4765EBC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4792EUS	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX4792EUS-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4902ETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4905ETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4951BECTP+GH7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX5547ETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX5556ESA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKLD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKLD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKRD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKRD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKSD3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKTD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKVD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKVD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKYD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D3S	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D3S-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK26D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKZD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6739XKZD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKLD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14707ENA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14707EVAL#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14708DEMBD#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14708EVAL#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14886CTL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14886EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14950ACTL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14950ACTL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14955ETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14955EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX15089EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX15577EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX15577GTG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16102H2310+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16102UK+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16104UT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16106V3111MB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16108W3110IA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16111A2916CA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16115O16MC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16117B4629OD+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16121BHIB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16841ASA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16841BUCKREF1	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16841EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16841EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17144ETJ+TC89	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17818EUE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19792ETX+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19792ETX+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK18D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK25D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK25D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK26D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK26D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK26D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK26D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK27D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK27D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK27D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK28D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK28D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK28D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK29D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK29D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK29D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK30D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK30D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK30D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK31D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK42D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK42D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK42D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK42D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK42D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK42D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK43D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK43D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK43D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK43D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK43D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK43D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK44D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK31D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK31D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK31D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK31D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK32D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK32D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK32D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKMD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKMD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKRD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKSD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKTD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKVD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKWD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKYD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKZD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKZD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6781LTB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6782TEB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6783TEA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6783TEC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6784TCB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6785TCB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6785TCC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6788TA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK29D3S-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D3S	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D3S-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6790TB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD0+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841EUKD0+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841EUKD1	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19792EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19793ETX+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19793EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2062ETM+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2062ETM+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2063ETM+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2063ETM+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2064ETM+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2064ETM+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2064EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2117CTI+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2117EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136BETJ/V+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136ETJ+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136ETJ/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX2136ETJ/V+Q00	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136ETJ/V+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2136EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AE/W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AE/W-B3N	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AE/W-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AETL+TW	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AETL+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163AEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ASEWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ASEWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ETI+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ETI/V+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ETIEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2163ETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2165ETI+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2165EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2169ETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2169ETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2169EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2180ETG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2202EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2202EWT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2202EWT+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2203EWT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2203EWT+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2664EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2664EWS+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2664EWS+T10	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2665EWS+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2665EWS+T10	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2666DEVBD	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2666EYT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2668DEVBD	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2668EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK20D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK20D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK33D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK33D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK33D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK34D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK34D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK34D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK35D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK35D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK35D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK36D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK36D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK37D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK37D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK37D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK45D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK45D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK45D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK45D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK45D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK45D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK46D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7049EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7443ESA+TG075	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7444D/B	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7444ETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7450EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7452ESA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK37D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK38D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK38D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK38D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK39D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK39D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK39D5+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK39D6+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK40D2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK40D4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK40D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841EUKD2	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841EUKD4	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841EUKD4-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841FUKD0-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841FUKD2	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841FUKD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6841FUKD4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841GUKD0+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841GUKD1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841GUKD2+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841GUKD4+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841HUKD0+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK32D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK32D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK32D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK32D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK32D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK32D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16104O4623+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX5556ESA/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2180ETG/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX19791ETX+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX17818EUE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16110O2309IB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2675EWT+T10	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2676EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2676EWT+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2676EWT+T10	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX3678U/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2769E/W-TGB6	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3679AE/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3679AE/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2837-RD0087	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3697C/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3697C/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2837ETM+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2837ETM+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3698C/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2837EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3698C/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2838ETM+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2838ETM+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2838EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3580ETJ+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3698C/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3580ETJ+TW	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3580ETJ+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3986EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3580EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3622C/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3622C/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3624AE/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3624AE/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3624U/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3625AC/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3625AC/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3625C/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3625C/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3627C/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3627C/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3636E/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3636EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3671E/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3671E/W+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX3673E/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3673ETN+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3677C/W+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3677C/W+G2K	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX3986UTU+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4079CUG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4079CWG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4079EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4763EBC	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK21D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK22D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6855UK44D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7461EUK+TG071	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7462USA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7462UUA-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7463USA+TW	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7474EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8847YETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8848YETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8848ZEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX8924EWN+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9503GETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9505ETE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9599AETG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9679AETG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695AETM+TCBV	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9695ETM+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701EBP+TG45	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9701ETG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+C8A	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9789AETJ+TGB4	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK44D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK45D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D1+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK46D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK16D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16110O2309IB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16111KA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16113B4623OD+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16113B4623OD+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16113KA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX16115O16MC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16115O31JA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16115O31JA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16115UT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16117B4629OD+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16117UT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16119H2307MC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16119H2307MC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16119KA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4763EBC-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4763ETC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AEBC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AETB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AETB+G104	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AETB+TG104	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4764AEUB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4765EBC	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4765EBC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4765EBC+G05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4765EBC+TG05	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4765EBC-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4765ETC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4792EUS+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4792EUS+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4902EBL	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4902EBL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4902EBL-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4902ETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4905EBL	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4905EBL-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4905ETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4951BECTP+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4951BECTP+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4951BECTP+TGH7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4951BEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX5547ETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX5556ESA	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX5556ESA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX5556ESA/V+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKLD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKLD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKLD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKMD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKMD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKMD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKRD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKRD3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKRD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKSD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKSD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKSD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKSD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKTD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKTD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKTD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKVD3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKVD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKVD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKWD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKWD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKWD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKYD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKYD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK25D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK27D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6844UKD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK17D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK37D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK38D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK23D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK40D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK41D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK29D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK30D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK44D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK34D5+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6855UK36D6+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7443EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK22D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK25D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK29D3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14619ETT+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16121BHIB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16121KA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16104B2916+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16104O4623+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16106O2309IB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16106UT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16108UT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16108W3110IA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14706ENA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14706ENA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX14707ENA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14708ENA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14708ENA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKZD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKZD3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKZD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKZD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKLD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKLD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKLD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKLD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKMD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKMD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKRD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKRD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKRD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKSD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKSD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKSD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKSD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKTD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKTD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKTD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKVD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKVD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKVD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKWD3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKWD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKWD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKYD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKYD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKYD7-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKZD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKZD3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6742XKZD7	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6781LTA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6781LTB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6781LTC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6781LTC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6782TEA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6782TEB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6782TEC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6782TEC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6783TEB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6783TEB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6783TEC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6784TCA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6784TCB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6784TCC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6784TCC+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6785TCA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6785TCB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6785TCC+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6786TA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6787TA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6787TA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6788TA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6789TB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D6S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK29D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK31D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D3S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX16841ASA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK16D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK26D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK27D1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK29D3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK29D4+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK31D3	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6858UK31D3-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK23D3S-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK24D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKLD3+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6739XKVD3+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK27D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK28D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6783TEA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK30D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK31D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841FUKD1	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14579AEETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14579BEETA+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14608EEWP+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14608EEWP+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6789TB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6790TB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD0	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD0+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD0-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD1	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD1+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD1-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD2	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6841DUKD2+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX6865UK33D1S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D2L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D2S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D4L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D5L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D5L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D6L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK33D6S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D1L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D1L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D1S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D2L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D2S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D3L+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D3L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D3S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D4L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D4S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D4S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D5S+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D5S+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX6865UK34D6L+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	ENGWV60EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500USA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11500USA+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11501USA+G51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11501USA+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11504CUB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11505CUB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11507CEE+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX11508UUD+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX13101EEBX	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13101EEWX+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13102EETL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13103EETL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX13374ASA/V+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14579AEETA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14596EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14609EEWP+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14631EKA+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14657ETE+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX14706DEMBD#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2170ETL+TCDQ	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2180AEVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839ASEWO+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839ASEWO+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839ASEWO+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839ETN+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839ETN+TG51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839ETN+W	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2842ETN+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2842ETN+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4827ELT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4827ELT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4827ELT-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4828ELT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4828ELT+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4828ELT-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7307ALB+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7307ALB+TG51	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7307EVCMAXQU+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7307EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606AEWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606BEVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606BEWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606BEWL+CEX	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606BEWL+TCEX	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX9606EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606EWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606SEWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606SEWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9688ETI+TC97	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9688EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9696ETG+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9699EWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9699EWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL+C6S	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL+CB0	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL+TC6S	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL+TG45	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717AEBL	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717AEBL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717AEBL-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717BEBL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717BEBL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717CEBL	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717CEBL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717CEBL-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717DEBL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717DEBL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98088EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98088EWY+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98314EVKIT#	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98314EWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98314EWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717BEBL	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717CEBL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98088EWY+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2170ETL+CDQ	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839ASEVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 08-Feb-2015

Discontinuance	MAX2839ETN+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2839EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX2842EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX4828ELT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7307ALB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX7307AUB+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606AEWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606BEWL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9606EWL+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9688ETI+C97	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9696ETG+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EBL+G45	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9716EVKIT	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717AEBL+T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717BEBL-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717DEBL	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX9717DEBL-T	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured
Discontinuance	MAX98314EVKIT+	N/A	10-Jul-2015	08-Jan-2017	Part can no longer be manufactured