



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000886

DATE: 17-Mar-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX15025BATB+	N/A			Part reactivated from prior notice: M000869
Reactivation	MAX4090AAUT+T	N/A			Part reactivated from prior notice: M000854
Discontinuance	806-0636-20-D	806-0636-20+D	17-Mar-2019	17-Mar-2019	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	DS3960IMV+	DS3960IMV#CQV	17-Mar-2019	17-Mar-2019	The part was not released
Discontinuance	DS3960IMV+W	DS3960IMV#CQV	17-Mar-2019	17-Mar-2019	The part was not released
Discontinuance	DS3961IMV+	DS3961IMV#CQX	17-Mar-2019	17-Mar-2019	The part was not released
Discontinuance	DS3961IMV+W	DS3961IMV#CQX	17-Mar-2019	17-Mar-2019	The part was not released
Discontinuance	MAX1037EKA-T	MAX1037EKA+T	17-Mar-2019	17-Mar-2019	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX14636EVB+T	MAX14636CVB+T	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX15001BEUB+	MAX15001AEUB+	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX1607ETB+TG38	N/A	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX20030ATMA/V+	MAX20030BATMA/V+	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX20030ATMA/V+T	MAX20030BATMA/V+T	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX20031ATMC/V+T	MAX20031BATMC/V+T	17-Mar-2019	17-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX30105EFD+	MAX30101EFD+	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX30105EFD+T	MAX30101EFD+T	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX3869ETJ+	MAX3869EHJ+T	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX4336EXT	MAX4336EXT+T	16-Mar-2020	15-Sep-2020	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX44009EDT+	N/A	17-Aug-2019	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX44009EDT+T	N/A	17-Aug-2019	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX5407EKA	MAX5407EKA+T	16-Mar-2020	15-Sep-2020	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX5474EKA	MAX5474EKA+T	16-Mar-2020	15-Sep-2020	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX6769TALD2/V+T	N/A	17-Mar-2019	17-Mar-2019	The part was not released
Discontinuance	MAX8685CEVKIT+	N/A	17-Mar-2019	17-Mar-2019	EVKIT is No Longer Supported
Discontinuance	MAX8685FETD+	N/A	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX8685FETD+T	N/A	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 17-Apr-2019

Discontinuance	MAX8685FEVKIT+	N/A	17-Mar-2019	17-Mar-2019	EVKIT is No Longer Supported
Discontinuance	MAX8831EWE+T	N/A	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX9288GTM+T	MAX9288GTM/V+T	17-Mar-2019	17-Mar-2019	The part was not released
Discontinuance	MAX9406EVKIT+	N/A	17-Mar-2019	17-Mar-2019	EVKIT is No Longer Supported
Discontinuance	MAX9830AETA+T	MAX98300ETA+T	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX9830AETA+TG2Z	MAX98300ETA+T	16-Mar-2020	15-Sep-2020	Part can no longer be manufactured
Discontinuance	MAX9938WEBS+T	MAX9938WEBS+TG45	16-Mar-2020	15-Sep-2020	The part was not released
Discontinuance	MAXQ1010-A01+	N/A	17-Mar-2019	17-Mar-2019	Part can no longer be manufactured
Discontinuance	MAXQ1010-DNS+	N/A	17-Mar-2019	17-Mar-2019	Part can no longer be manufactured
Discontinuance	SC-USB-SPI	SC-USB-SPI-PICO	17-Mar-2019	17-Mar-2019	EVKIT is No Longer Supported