



Final Product Change Notification **Update**

202007035F01U01 : i.MX RT1060 New Silicon Revision With New Part Number

Note: This notice is NXP Company Proprietary.

Issue Date: Mar 02, 2022 **Effective date:** Mar 03, 2022

Here is your personalized notification about a NXP general announcement.
For detailed information we invite you to view this notification online

Management summary

i.MX RT1060 maskset revision 1N00X which has been qualified with new part number MIMXRT106xxxxxB.

Change Category

<input type="checkbox"/> Wafer Fab Process	<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Product Marking	<input type="checkbox"/> Test Process	<input checked="" type="checkbox"/> Design
<input type="checkbox"/> Wafer Fab Materials	<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Equipment	<input type="checkbox"/> Errata
<input type="checkbox"/> Wafer Fab Location	<input type="checkbox"/> Assembly Location	<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Location	<input type="checkbox"/> Electrical spec./Test coverage
<input type="checkbox"/> Firmware	<input type="checkbox"/> Other			

PCN Overview

Description

NXP Semiconductors is announcing i.MX RT1060 maskset revision 1N00X which has been qualified with new part number MIMXRT106xxxxxB.

The new mask revision has the below improvement:

Fixed ERR050101 USB: Endpoint conflict issue in device mode. An endpoint conflict occurs when the USB is working in device mode during an isochronous communication.

Please contact your NXP sales or marketing representative for additional information.

Reason

The release of i.MX RT1060 new maskset 1N00X fixed ERR050101 USB: Endpoint conflict issue in device mode.

Identification of Affected Products

Top Side Marking

Please refer to enclosed attachment

Product Availability

Sample Information

Samples are available from Aug 31, 2020

Below are the sample part numbers that will be made available.

MIMXRT1061DVL6B

MIMXRT1062DVL6B

MIMXRT1061CVJ5B

MIMXRT1062DVJ6B

MIMXRT1061CVL5B

MIMXRT1062CVL5B

Production

Planned first shipment Dec 31, 2020

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Disposition of Old Products

Existing maskset revision 0N00X inventory will be shipped until depleted.

Timing and Logistics

In compliance with JEDEC J-STD-046, your acknowledgement of this change is expected by Apr 01, 2022.

Update Information

Only the replacement 12NCs are added for customer information.

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply .

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2022 NXP Semiconductors. All rights reserved.

Changed Orderable Part#	12NC	New Orderable Part#	12NC New
MIMXRT106ADVL6A	935385521557	MIMXRT106ADVL6B	935399817557
MIMXRT106SDVL6A	935389819557	MIMXRT106SDVL6B	935399822557
MIMXRT106LDVL6A	935389818557	MIMXRT106LDVL6B	935399821557
MIMXRT106FDVL6A	935389817557	MIMXRT106FDVL6B	935399819557
MIMXRT106CDVL6A	935389816557	MIMXRT106CDVL6B	935399818557
MIMXRT106ADVL6AR	935385521518	MIMXRT106ADVL6BR	935399817518
MIMXRT1062DVL6A	935373204557	MIMXRT1062DVL6B	935394383557
MIMXRT1062CVL5A	935373203557	MIMXRT1062CVL5B	935394381557
MIMXRT1061CVL5A	935373201557	MIMXRT1061CVL5B	935394376557
MIMXRT1061CVJ5A	935379986557	MIMXRT1061CVJ5B	935394375557
MIMXRT1062DVJ6A	935379988557	MIMXRT1062DVJ6B	935394382557
MIMXRT1062CVJ5AR	935379987518	MIMXRT1062CVJ5BR	935394379518
MIMXRT1062CVJ5A	935379987557	MIMXRT1062CVJ5B	935394379557
MIMXRT1061DVJ6A	935386102557	MIMXRT1061DVJ6B	935394377557
MIMXRT1061CVJ5AR	935379986518	MIMXRT1061CVJ5BR	935394375518
MIMXRT1061DVL6A	935373202557	MIMXRT1061DVL6B	935388058557