

## Product Change Notice

Issue Date: 18 June 2021

**Change Description:**

Change of LED marking orientation in carrier tape

**Parts Affected:**

HSMH-A100-L00J1	HSMH-A100-N00J1	HSMH-A100-G50L2	HSMH-A100-P70J1
-----------------	-----------------	-----------------	-----------------

**Description and Extent of Change:**


Devices are reeled so that cathode is oriented properly with the direction of feed and round sprocket holes.

**Reasons for Change:**

To standardize device orientation for Broadcom PLCC LEDs.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There will be no change on fit, form, function, quality and reliability of final product except the LED orientation in carrier tape as illustrated below



**Effective Date of Change:**

Parts with above change will commence 90 days after issuance date above.

**Qualification Data:**

No change in reliability performance. Product and qualification data will be available upon request.

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.