



CUSTOMER OPERATIONS  
 160 RIO ROBLES  
 SAN JOSE, CA 95134

PDN #: M000841-RSP

DATE: 29-Aug-2016

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAXQ1741-KIT#	N/A	29-Aug-2016	29-Aug-2016	EVKIT is No Longer Supported
Discontinuance	MAXQ1850-ENS+T	N/A	28-Feb-2017	29-Aug-2018	Part can no longer be manufactured
Discontinuance	MAXQ1850-KIT#	N/A	29-Aug-2016	29-Aug-2016	EVKIT is No Longer Supported
Discontinuance	MAXQ3180-KIT	N/A	29-Aug-2016	29-Aug-2016	EVKIT is No Longer Supported
Discontinuance	MAXQ3180-RAN+	N/A	28-Feb-2017	29-Aug-2018	Part can no longer be manufactured
Discontinuance	MAXQ3180-RAN+T	N/A	28-Feb-2017	29-Aug-2018	Part can no longer be manufactured
Discontinuance	MAXQ3181-RAN+	N/A	28-Feb-2017	29-Aug-2018	Part can no longer be manufactured
Discontinuance	MAXQ3183-RAN+	N/A	28-Feb-2017	29-Aug-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Sep-2016