



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000844

DATE: 08-Nov-2016

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	DS5000-32-16	DS5000-32-16+	08-Nov-2017	08-Nov-2018	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	DS5000T-32-16	DS5000T-32-16+	08-Nov-2017	08-Nov-2018	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX1487C/D	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Lead-Free Conversion	MAX1840EUB	MAX1840EUB+	08-Nov-2017	08-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX19695EVKIT#	N/A	08-Nov-2017	08-Nov-2018	EVKIT is No Longer Supported
Lead-Free Conversion	MAX211EC/D	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Lead-Free Conversion	MAX232AC/D	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Lead-Free Conversion	MAX3318C/D	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Lead-Free Conversion	MAX491C/D	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Lead-Free Conversion	MAX5024MASA	MAX5024MASA+	08-Nov-2017	08-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5024TASA	MAX5024TASA+	08-Nov-2017	08-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX563C/D	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Lead-Free Conversion	STM1E-SFP25	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	806-0727-20+T	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1220Y-120+	DS1220AD-100+	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	DS1220Y-150+	DS1220AD-100IND+	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	DS1220Y-200IND+	DS1220AD-100IND+	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	DS1393U-18+	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1925A-F5#	N/A	08-Nov-2016	08-Nov-2016	Part is leaded. Request information on lead-free version
Discontinuance	DS21Q352	N/A	08-Nov-2017	08-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS21Q354BN	N/A	08-Nov-2017	08-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	DS2762BX-025/T&R	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS3112N+	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4160D+	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4160P+	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+100/100	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 09-Dec-2016

Discontinuance	DS4625P+100/150	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+125/125	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+125/156	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+150/150	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4625P+150/200	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	DS5000-32-16+	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	DS5000T-32-16+	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	DS5002FMN-16+	N/A	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX1108EUB+G07	MAX1108EUB+	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX13085EASA+	MAX13085EESA+	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX13085EASA+T	MAX13085EESA+T	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX15301AA01+CK	MAX15301AA02+CJK	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX16908XAUE/V+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX16932BATIS/V+	MAX16932CATIS/V+	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX17023BAUI/V+	MAX17023CAUI/V+	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX17023BAUI/V+T	MAX17023CAUI/V+T	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX20003ATPA/V+GE	MAX20003ATPA/V+	08-Nov-2016	08-Nov-2016	The part was not released
Discontinuance	MAX20003ATPA/V+TGE	MAX20003ATPA/V+T	08-Nov-2016	08-Nov-2016	The part was not released
Discontinuance	MAX20081WATN/V+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX2117EVKIT+	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2206EVKIT	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2209AEVKIT+	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2209EVKIT+	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX2242EVKIT	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX225CWI+TG36	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX225EWI+G36	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX3266CSA	N/A	08-Nov-2017	08-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	MAX3761EEP	MAX3761EEP+	08-Nov-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX436EPD+	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX471CPA+	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX498CWI+	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX6972EVKIT	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX7306ALB+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX7306ALB+T	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX7306AUB+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX7306AUB+T	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 09-Dec-2016

Discontinuance	MAX7432EUD	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX7445EUD+	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX7461EUK+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX88200EFD+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX88200EFD+T	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX9124EUE+	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX9503MEEE+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX9503METE+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX9668ETP+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX9669EVKIT+	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAX9679BETG+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX9713EVKIT+	N/A	08-Nov-2016	08-Nov-2016	EVKIT is No Longer Supported
Discontinuance	MAXQ2000-RAX+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAXQ2000-RBX+	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAXQ616V-L000+T	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	MAXQ616V-L001+T	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	VT1323SFC	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	VT1323SFC	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	VT1324SFCR	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	VT1324SFCR	N/A	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	VT370FCX-ADJ	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	VT371FCR-ADJ	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	VT371FCX-ADJ	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	VT384BFCR-ADJ-001	VT384BFCX-ADJ-001	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	VT385FCX-ADJ	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured
Discontinuance	VT387BFCR-ADJ	VT387BFCX-ADJ	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	VT388BFCR-ADJ	VT388BFCX-ADJ	08-Nov-2016	08-Nov-2016	Part can no longer be manufactured
Discontinuance	VT388FCX-ADJ-001	N/A	10-May-2017	08-Nov-2018	Part can no longer be manufactured