

Product Change Notification

TE Connectivity

Product Change Notification: E-17-001839

PCN Date: 13-FEB-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:	
EVC500 RELAY	

Description of Changes

The following part numbers are being obsoleted (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application- Drawings are available via TE.com. PCN P-17-014081 = 2098372-1 replaced by 2219561-1; PCN P-17-014060 = 2203511-1 replaced by 2312217-1, 2203512-1 replaced by 2312217-2, 2272161-1 replaced by 2312219-1; PCN P-17-014039 = 2098190-1 replaced by 2299223-2, 2272991-2 replaced by 2299223-2, 2272991-1 replaced by 2299223-1

Reason for Changes:					
Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter. See PCN P-17-014039, P-17-014060, P-17-014081					
Estimated Dates:					
Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):					
15-SEP-2017					
.ast Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only):					
27-OCT-2017	No Mixed Shipments				

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>2098190-1</u>	YES				2299223-2		manufacturing
2098190- 1	YES				2299223-2		manufacturing

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
<u>2098190-1</u>	2098190-1		D	

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
2098190-1	YES				2299223-2		manufacturing location

Part Number(s) being Modified:

. are rained	(c) boing moundai						
Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
2098190-1	YES				2299223-2		

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
		-					manufacturing location

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
<u>2098190-1</u>	2098190-1		D	