



CUSTOMER OPERATIONS  
 160 RIO ROBLES  
 SAN JOSE, CA 95134

PDN #: M001028

DATE: 16-Jan-2021

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS21448L+	N/A	18-Mar-2021	14-Sep-2021	Part can no longer be manufactured
Discontinuance	DS21448LN+	N/A	18-Mar-2021	14-Sep-2021	Part can no longer be manufactured
Discontinuance	MAX16065ETM+	N/A	16-Jan-2022	15-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16065ETM+T	N/A	16-Jan-2022	15-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16070ETL+	N/A	16-Jan-2022	15-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX16071ETL+	N/A	16-Jan-2022	15-Jul-2022	Part can no longer be manufactured
Discontinuance	MAX2982GCD/V+	N/A	18-Mar-2021	14-Sep-2021	Part can no longer be manufactured
Discontinuance	VT1175SFQX	N/A	16-Jan-2022	15-Jul-2022	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 16-Feb-2021